


IN THE DRAWINGS

A "replacement sheet" is submitted herewith (Fig. 2) in order to correct an error in the drawings as originally filed. No new matter was added in making these corrections.

In the original Figure 2, the elements to be replaced represent DIAC-diodes, which obviously for a person skilled in the art cannot be used in such circuitry. Hence, a person skilled in the art will automatically replace the DIAC-diodes with capacitors as shown in the corrected Figure 2.

Also enclosed is a red-lined version of the drawings showing the corrections. Any inquiries regarding this paper may be directed to the undersigned attorney at the telephone number listed below.

Respectfully Submitted,



Robert C. Klinger  
Reg. No. 34,365  
Attorney for Applicant

Jackson Walker L.L.P.  
2435 North Central Expressway, Suite 600  
Richardson, Texas 75080  
(972) 744-2933  
(972) 744-2909 (Fax)